




Esso Italiana S.p.A.
una società del gruppo EXXON

Raffineria di Augusta

C.P. 101 - 96011 Augusta (SIRACUSA)
Telefono 0931/987111
Telex: 970030 Augraf (DIREZ.)
Telex: 970265 Augraf (DIREZ.)
Telex: 970122 Augmag (APPR.)
Telegraf. Raffinesso

Capitale L. 122.800.000.000
interamente versato
Sede centrale: Roma
Sede legale: Genova
c.c.i.a. Genova 776
c.c. postale n. 362012
Tribunale di Genova
N. 2670 Reg. Società
N. 8355/77 Reg. fasc.

Codice fiscale 00473410587
Partita IVA 00902231000



TO WHOM IT MAY CONCERN

ESSO 1996 FCC TURNAROUND
AUGUSTA REFINERY, ITALY

Remosa supervised the works for the refurbishing of the following valves during the above turnaround :

- a. N 1 Diversion flue gas valve
7' - 1" I.D. S.A. 285 Gr. C
- b. N 1 Double disc flue gas valve
77" I.D. S.A. 515 Gr. 70
- c. N 1 Double disc flue gas valve
68" I.D. S.A. 515 Gr. 70
- d. N 1 Regenerated catalyst slide valve
45" I.D. S.A. 304 H
- e. N 1 Spent catalyst slide valve
45" I.D. S.A. 387 Gr. 11 cl. 2

The repair works were performed on the field within the Esso FCC unit and consisted of :

1. Removal of internal parts
2. Replacement of internal parts
3. Calibration of actuators

A special machine tool was designed by Remosa engineering department to perform the repair works inside the 68" double disc flue gas valve without removing it from the line.

All refurbishing was performed in compliance with Esso requirements with full satisfaction of operative personel and technical staff.

Esso Augusta Refinery recommend Remosa for the excellent performance of the job done and high professionalism of their staff.

Yours sincerely

Michele Costa
Maintenance Dept.