



شركة بترومين - موبيل المحدودة لمصفاة ينبع
Petromin-Mobil Yanbu Refinery Company Ltd.

C. R. 47001240
CAPITAL S R 1900,000,000 FULLY PAID

سجل تجاري 17001240
رأس المال المدفوع بالكامل 1,900,000,000 ريال سعودي

المكتب الرئيسي:
صندوق بريد رقم 30078
مدينة ينبع الصناعية
المنطقة 1000 - 396 (01)
الفاكس: 662325 - حرف اس جي

HEAD OFFICE
PO BOX 30078
YANBU AL SINAIYAH
SAUDI ARABIA
TEL 1041 396 4000
TELE X 662325 PEMREF SJ

REMOSA S.p.A.
Segreteria Direzione
Viale Pula 37, 009100 Cagliari
Italy

06 February 1992G

Subject: PEMREF 1992 F.C.C. TURNAROUND
YANBU AL-SINAIYAH, SAUDI ARABIA

Gentlemen:

During the subject turnaround the FCC slide valves were overhauled by REMOSA.

The overhaul consisted of:

- 1) No. 1 Double Disk Flue Gas
Slide valve 2295.4mm O.D. x 2295.4 O.D., S.S. TP 304H.
- 2) No. 1 Re-circulated Catalyst
Slide valve 1612mm O.D. x 1762mm O.D., S.S. TP 304H.
- 3) No. 1 Regenerated Catalyst
Slide valve 1282mm O.D. x 1440mm O.D., S.S. TP 304H.
- 4) No. 1 Spent Catalyst
Slide valve 1272mm O.D. x 1440mm O.D., 1-1/4%cr - 1/2MO A387 Gr. 11 cl.2

These valves are the welded body type along with being welded to the line.

All refurbishment were field executed within Pemref FCC unit.

The refurbishment tasks consisted of:


- 1) Removal of all slide valves internal parts.
- 2) Replacing internal parts.
- 3) Calibration of actuators.

All tasks were conducted in a punctual safe manner, in keeping with Pemref requirements.

Pemref is impressed with REMOSA's professionalism, flexibility and quality of their staff.

We would not have any hesitation in recommending REMOSA to any future prospective company.

Very truly yours,
Petromin-Mobil Yanbu Refinery Co., Ltd.


J.S. Anacker
Maintenance Manager